



ERRATA SHEET DS21554/DS21Q554

Revision C1 Errata

The errata listed below describe situations where DS21554 revision C1 and DS21Q55 revision C1 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS21554 revision C1 and DS21Q55 revision C1 components. Revision C1 components are branded on the topside of the package with a six-digit code in the form yywwC1, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS21554 die revision, visit our website at www.maxim-ic.com/errata.

There are no known errata for this revision of the device.

*DS21554/DS21Q554
REV C1 ERRATA*

Revision History

REVISION DATE	DESCRIPTION	PAGES CHANGED
100305	(initial release) Two known errata: 1) SLC-96 MESS5 Message Corruption in T1 D4 Framing 2) Failure to Detect J1 LFA (Yellow Alarm) in ESF Mode	—
080508	No known errata.	1