



## DS5001FPM 128k Soft Microprocessor Chip

[www.maxim-ic.com](http://www.maxim-ic.com)

### REVISION C9 ERRATA

The errata listed below describe situations where DS5001FPM revision C9 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS5001FPM revision C9 components. Revision C9 components are branded on the topside of the package with a six-digit code of the form yywwC9, where yy and ww are two-digit numbers representing the year and work-week of manufacture, respectively. To obtain an errata sheet on another DS5001FPM die revision, visit the website at [www.maxim-ic.com/errata](http://www.maxim-ic.com/errata).

**There are no errata on this revision of the device.**