



ERRATA SHEET DS32506/DS32508/DS32512

Revision A2 Errata

The errata listed below describe situations where DS32506/DS32508/DS32512 revision A2 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS32506/DS32508/DS32512 revision A2 components. Revision A2 components are branded on the topside of the package with a six-digit code in the form yywwA2, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS32506/DS32508/DS32512 die revision, visit our website at www.maxim-ic.com/errata.

There are no known errata for this revision of the device.