



# DS5002FP

## Secure Microprocessor Chip

[www.maxim-ic.com](http://www.maxim-ic.com)

### REVISION C7 ERRATA

The errata listed below describe situations where DS5002FP revision C7 components perform differently than expected or differently than described in the data sheet. Dallas Semiconductor intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS5002FP revision C7 components. Revision C7 components are branded on the topside of the package with a six-digit code of the form yywwC7, where yy and ww are two-digit numbers representing the year and work-week of manufacture, respectively. To obtain an errata sheet on another DS5002FP die revision, visit the website at [www.maxim-ic.com/errata](http://www.maxim-ic.com/errata).

**There are no errata on this device.**