



ERRATA SHEET DS8007

Revision A6 Errata

The errata listed below describe situations where DS8007 revision A6 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata in subsequent die revisions.

This errata sheet only applies to DS8007 revision A6 components. Revision A6 components are branded on the top side of the package with a six-digit code in the form yywwA6, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS8007 die revision, visit our website at www.maxim-ic.com/errata.

There are no errata on this revision of the device.