



## ERRATA SHEET DS5250

---

### Revision A2 Errata

*The errata listed below describe situations where DS5250 revision A2 components perform differently than expected or differently than described in the data sheet. Maxim Integrated Products, Inc., intends to correct these errata when the opportunity to redesign the product presents itself.*

*This errata sheet only applies to DS5250 revision A2 components. Revision A2 components are branded on the topside of the package with a six-digit code in the form yywwA2, where yy and ww are two-digit numbers representing the year and work week of manufacture, respectively. To obtain an errata sheet on another DS5250 die revision, visit our website at <https://support.maxim-ic.com/micro>.*

**There are no errata on this revision of the device.**